



2 July 2025

Dear Parents and Staff of Seacoast Classical,

New Hampshire state law RSA 485:17-a requires school and child care facilities to test for lead in drinking water and to act when lead is found at levels at or above 5 parts per billion (ppb). Seacoast Classical Academy did a round of this testing when we opened, and we have recently done another round of testing after our landlord performed some water-system-remediation work.

As part of our preparation of our schoolhouse, we replaced a pre-existing drinking fountain and bottle filler with a new pair of side-by-side drinking-fountain and bottle-filler fixtures. In addition, all of the hand-washing water fixtures in the schoolhouse are either replacements or new fixtures. Even though these hand-washing fixtures are not intended to provide drinking water, we subject them to testing.

The test results for the latest round of testing are below. All sample results and additional resources from the New Hampshire Department of Environmental Services (NHDES) can be viewed at gettheleadoutnh.org.

Outlet Number	Location	Sample Result	Remediation
R130002-1	Girls' bathroom left faucet	2.04 ppb	Not Applicable
R130002-2	Girls' bathroom middle faucet	2.18 ppb	Not Applicable
R130002-3	Girls' bathroom right faucet	2.14 ppb	Not Applicable
R130002-4	Boys' bathroom left faucet	4.76 ppb	Not Applicable
R130002-5	Boys' bathroom middle faucet	31.3 ppb	Post "Hand Washing Only" sign
R130002-6	Boys' bathroom right faucet	5.00 ppb	Post "Hand Washing Only" sign
R130002-7	Nurse's bathroom faucet	2.39 ppb	Not Applicable
R130002-9	Middle School Girls bathroom	None detected	Not Applicable
R130002-10	Middle School Boys bathroom	None detected	Not Applicable
R130002-11	Kindergarten A bathroom	None detected	Not Applicable
R130002-12	Kindergarten B bathroom	None detected	Not Applicable
R130002-13	Nurse station sink	None detected	Not Applicable
R130002-14	Teachers room sink	1.54 ppb	Not Applicable
R130002-15	Hallway drinking fountain low	None detected	Not Applicable
R130002-16	Hallway drinking fountain high	None detected	Not Applicable

Lead levels are elevated (at or above 5 ppb) at 2 of our 13 water faucets. These two faucets are in the boys bathroom. I have kept a "Hand Washing Only" sign at these two bathroom faucets. There was no lead detected in the water from our drinking fountains. Back on March 14th, out of an abundance of caution I closed our drinking fountains even though they have never shown any detectable lead in any

test, including the latest round of testing. I have now reopened the drinking fountains, and they will be in service in August when our staff and scholars return.

Sincerely,

Timothy Galitski, PhD

Executive Director and Founder